

	INSPECTION REPORT Pre-Shipment Inspection	Report No. :H-XXXXX
---	---	---------------------

INSPECTION INFORMATION			
Client	XXXXXX		
Supplier	XXXXXX		
Factory	XXXXXX		
Inspection Instruction	GWI-E-003-HQT;		
P.O. No.	TSC/0005/13	Sampling Plan	ISO 2859, Single, Normal
Item No.	XXXXXX	Sampling Level	Level II
Inspection Date	XXXXXX	Sample Size	200 Pieces
Inspection Location	XXXXXX	AQL	Cr:0, Maj:1.0, Min: 4.0
Product description	Mobile Phone		



INSPECTION RESULT SUMMARY			
Category	Conform	Not Conform	Pending
1.Quantity	x		
2.Workmanship		x	
3.Style, Color & Documentation	x		
4.Field Test & Measurement			x
5.Shipping Mark & Packaging	x		
OVERALL CONCLUSION NOT CONFORM to client's requirement			

This report reflects the facts as recorded by HQTS at the time and place of inspection. It does not relieve the manufacturers from their contractual obligations nor prejudice client's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter.

SPECIAL ATTENTION POINT (SAP)

1	Quantity	NIL
2	Workmanship	NIL
3	Style, Color & Documentation	NIL
4	Field Test & Measurement	
4.1	For SIM card check, the "SIM registration failed" displayed on screen when using manufacturer SIM card.	
5	Shipping Mark & Packaging	NIL

INSPECTION DETAILS

1.Quantity					Conform			
PO No.	Item No.	P.O. Qty	Shipment Qty		Packing Qty		Sample Size	
		(Pieces)	(Pieces)	(Cartons)	(Pieces)	(Cartons)	(Pieces)	(Cartons)
TSC/0005/13	XXXXX	5000	5000	500	5000	500	200	25
Total		5000	5000	500	5000	500	200	25

2.Workmanship		Not Conform		
Defects Description		Critical	Major	Minor
Missing battery cover		-	1	-
Manufacturer rework sticker on unit		-	1	-
Different number between IMEI sticker and the sticker in unit		-	4	-
Missing protective film on camera		-	2	-
Missing one IMEI sticker		-	1	-
Slightly turn up of USB sokect cover		-	-	2
Slightly blurry on one IMEI sticker		-	-	1
Total Found:		0	9	3
Allowed:		0	5	14

Defect Photos



Missing battery cover



Manufacturer rework sticker on unit



Different number between IMEI sticker and the sticker in unit



Missing protective film on camera



Missing one IMEI sticker



Slightly turn up of USB socket cover

3.Style, Color & Documentation		Conform		
DESCRIPTION		Conform	Not Conform	Pending
The inspected samples were consistent with		-	-	-
Product Specification		x		
Digital photo		x		
Instruction manual and document verification		-	-	-
Instruction manual in English.		x		

4.Field Test				Pending		
Item		Specification	Sample Size	Conform	Not Conform	Pending
1)	Function check		200 Samples			x
2)	Internal check for workmanship		2 Samples	x		
3)	Power on for 4 hours		2 Sample	x		
4)	Rub and Tape test		2 Samples	x		
5)	Product measurement		2 Samples	x		
6)	Dimension of carton		1 Cartons			x
7)	Weight of carton		1 Cartons			x
8)	Transportation drop check		1 Cartons			x

SAMPLE

Measured Data was listed as below table:

checking item	specification	actual
Dimension of export carton (+/-5%)	83x75.5x52 cm	83x76x53 cm
Weight of export carton (+/-10%)	62 kg	62.5 kg
Product size (cm)	-	135.7x 62.1x15 mm
Product net weight (g)	124	122.5, 122.8, 121.8, 121.7, 122.6

5.Shipping Mark & Packaging

Conform

1) Shipping mark photos

XXXXXX	XXXXXX
--------	--------

2) Packaging photos

XXXXXX	XXXXXX
--------	--------

6.Reference Note

1)	Carton No. was not assigned yet
2)	Total 1 inspected carton was sealed with "HQTS" sticker.
3)	Manufacturer did not allow us to draw any production sample for reference.
4)	The weight check was conducted by using the testing appliance without verification which was provided by the factory.

7.Photos



Inspector: 881

Auditor: 071

End of Report